

GLOBAL Rotax MAX Challenge Technical Regulation 2021

Bulletin no.: 02

Valid as of: 2021 05 04

Addendum/Changes (highlighted in yellow) compared to Global RMC
Technical Regulation 2021, Edition 2021 03 03 Version 4

The new cylinder protection plate ROTAX part no. 251336 will be optional to be installed. The protection plate (45) was added to the illustration on the right.

Please find the changes to the regulations below:

6.6. Exhaust valve (125 Senior MAX and 125 MAX DD2)

System must be used with all components fitted as shown in the illustration below.

Bellow (8) must have green colour.

The cylinder protection plate (45) is optional to be installed and must have a minimum thickness of 0,08 mm.

It is possible for the cylinder protection plate (45) to show signs of wear or damage.

Bellow (10) must have green colour.

